



Sposób montażu / Installation method / Метода монтажа


- 2. Montaż bezpośredni
- 2. Surface mounting
- 2. Поверхностный монтаж



6 LVM OUTSIDE POWER SUPPLY CONDUCTIVE MODULE

plastic


10168



7 LVM STRAIGHT CONDUCTIVE MODULE

plastic


10167



8 LVM CORNER CONDUCTIVE MODULE

plastic

10166




9 LVM INSIDE CORNER

aluminum

10165

includes 2xLVM TRACK BUCKLE CONNECTOR




10 LVM HORIZONTAL CORNER

aluminum

10164


includes 2xLVM TRACK BUCKLE CONNECTOR



11 LVM TRACK BUCKLE CONNECTOR

steel

10171



5 LVM 48V, 150W, INSIDE POWER SUPPLY

aluminum

10161